## Virtual Serial Port Installation (USB Connection Only)

When connect the receipt printer to the computer with USB cable, the computer will found a new hardware and then initiate the Found New Hardware Wizard automatically (as image below illustrated):


| USB | RS-232 | RJ-45 | RJ-11 | PWR |

Printer Cable (USB)   **Cash Drawer**   **Power Adaptor**

1. Found New Hardware Wizard is initiated; click "Install from a specific location (Advanced) and then click "Next" to continue.

2. To specify the location of driver, click "include this location in the search and "Browse" the specified folder manually.

3. Browse the subfolder of the path:" \\Receipt Printer\PRP188_250 Printer_USB_COM" (x86 for Windows XP 32 bit version). Click "OK" to continue.

4. The location of the driver is specified.
Click "Next" to continue.

5.　　Start Notification. Click "Continue Anyway" to continue.

6.   The wizard is installing the driver.

Found New Hardware Wizard

Please wait while the wizard installs the software...

Virtual serial port

Setting a system restore point and backing up old files in case your system needs to be restored in the future.

< Back   Next >   Cancel

7. The driver of Virtual Serial Port is successfully installed. Click "Finish" to finish.